

Description of incident:

TEMPSC fall chain noted as failed during routine planned inspection. Fall chain failure due to hydrogen embrittlement after prolonged exposure to adverse environment.

Description of Process:

Falls chain inspection conducted on 6 monthly intervals by competent inspector to PEWER standard.



Good Practice Guidance:

Falls chain to be inspected to LOLER and have defined replacement period not exceeding 5 years.