

## Description of incident:

- An individual came across some old scaffold 'feet' which had corroded, come away from the scaffold tube laying loose on grating near an air intake.
- In high winds, the debris could have caused injury or damage to equipment.
- The loose debris was removed and placed in the metal skip.

## Good Practice

- Carry out regular checks on legacy scaffolding – the tubes in this location had been placed to hold back a ladder and most likely not on the register

## Line of Fire

### Keep yourself and others out of the line of fire



- I position myself to avoid:
  - moving objects
  - vehicles
  - pressure releases
  - dropped objects
- I establish and obey barriers and exclusion zones
- I take action to secure loose objects and report potential dropped objects